


Table 1: Average concen trations of metals in the earth crust with the average concentrations exploited by mining and the enrichment factors. Some concentrations of element still present in mine tailings are shown to highlight the still strong enrichment of these elements in the waste material. Modified after (Evans, 1993).

Ø Crust	Ø by mineral	Enrichment	Ø In mine	Enrichment
(%)	exploitation (%)	Factor	tailings	Factor tailings
0.005	0.4	80	0.1 - 0.3	20 - 60
0.007	0.5	71	0.2	28.4
0.007	4	571	2-4	275 - 571
0.09	35	389		
0.0002	0.5	2500		
0.01	30	3000		
0.001	4	4000	1 - 2	1000- 2000
0.0000004	0.0001	250		
	(%) 0.005 0.007 0.007 0.09 0.0002 0.01 0.001	(%) exploitation (%) 0.005 0.4 0.007 0.5 0.007 4 0.09 35 0.0002 0.5 0.01 30 0.001 4	(%) exploitation (%) Factor 0.005 0.4 80 0.007 0.5 71 0.007 4 571 0.09 35 389 0.0002 0.5 2500 0.01 30 3000 0.001 4 4000	(%) exploitation (%) Factor tailings 0.005 0.4 80 0.1 - 0.3 0.007 0.5 71 0.2 0.007 4 571 2 - 4 0.09 35 389 0.0002 0.5 2500 0.01 30 3000 0.001 4 4000 1 - 2

(Dold, 2008; RESB)

Sequential Extraction

Classification after Jambor (1994):
primary mineralogy
secondary mineralogy
reteriary mineralogy
quartinary mineralogy
Dold (2003); JGE





Conclusions

Biomining in leach dumps in giant Cu mining is extremely ineffective

(70-90 % of the resource remains untouched!)

Criteria for bioleaching is ore grade, NOT mineralogy!!!

Principally only acid soluble Cu is leached

Real bioleaching of chalcopyrite is not reached.

Leach dumps do not have impermeable basement!

Potential

Convince the mining operation that:

- 1. They can do better (difficult with the actual metal prices!)
- 2. Characterization of the ore in order to build segregated deposits for optimized recovery
- 3. To built the deposit in order to increase temperature to reach 50-60°C (thermophile archea)
 - 4. Additional heat source is needed (pyrite?)
 - 5. Control of Temperature and air flow in the system
 - 6. Control of PLS on long-term
 - 7. Control of secondary mineralogy and chemistry of the solution is needed to prevent precipitation and inhibitation
 - 8. Search for additional values in the material and development of extraction techniques